

CONSOLIDATED AIRCRAFT SUPPLY CO., INC.
55 RAYNOR AVE., RONKONKOMA, NY 11779

FAA REPAIR STATION #GI1R167K
DATE 11/23/2011 JOB# 118340

COMPONENT TEARDOWN REPORT (Q.C. 261)

NOMENCLATURE: PUMP	WORK PERFORMED: OVERHAULED
PART NUMBER: 2070C.01	CUSTOMER: CORPORATE AIR
SERIAL NUMBER: 1616	CUSTOMER P.O.#: P011-01062
AMEND./MOD. Plate Status: N/A	MANUFACTURER: INTERECHNIQUE
REQUESTED/REQUIRED MODIFICATION: YES _____ NO <u>X</u>	REVISED PART #: N/A REVISED SERIAL #: N/A

AIRWORTHINESS DIRECTIVE SEARCHED BY JWR (TECH'S INITIALS) A.D. FOUND: YES _____ (COMPLETED BLOCK 6) NO X

1) RECEIVING REMARKS: (CUSTOMER INSTRUCTIONS, AIRCRAFT REMOVAL INFO, T.S.O. T.S.N.)

DUE OVERHAUL

2) TEARDOWN REMARKS:

UNABLE TO PRE-TEST DUE TO CONDITION. TEARDOWN FOUND UNIT INTERNALLY CARBON CONTAMINATED, BRUSHES WORN AND BEARINGS ROUGH. FURTHER EXAMINATION FOUND SEALS AND PACKING WORN.
OVERHAUL REQUIRED AT THIS TIME

N.D.T. REQ'D.: YES _____ NO X

3) REPAIR ACTION TAKEN:

REPLACED ALL DEFECTIVE PARTS AND OVERHAULED THE PUMP IN ACCORDANCE WITH THE SERVICE MANUAL.

4) INSPECTION REMARKS: (EXPLAIN P/N OR S/N CHANGES)

OVERHAULED & TESTED



ALL WORK DONE IN ACCORDANCE WITH C.M.M.#: 2070C01 REV 2 2/1988

5) SERVICE BULLETINS COMPLIED WITH:

N/A

6) A.D. COMPLIED WITH THIS SHOP VISIT: A.D.# N/A
A.D. ALREADY COMPLIED WITH: YES N/A NO N/A

TECHNICIAN'S SIGNATURE